















9001621983 (010209)














de	Montageanleitung	fi	Asennusohjeet
en	Installation instructions	et	Paigaldusjuhised
fr	Notice d'installation	lt	Įrengimo instrukcijos
it	Istruzioni d'installazione	lv	Uzstādīšanas instrukcijas
nl	Installatie-instructies	pl	Instrukcje montażu
es	Instrucciones de montaje	hu	Telepítési útmutató
pt	Instruções de instalação	cs	Pokyny k instalaci
el	Οδηγίες εγκατάστασης	sl	Navodila za montažo
da	Installationsvejledning	uk	Інструкція з монтажу
no	Installasjonsveiledning	kk	Орнату нұсқаулықтар
sv	Installationsanvisningar	ru	Инструкция по установке




















Torx
T 20












Torx
T 20








180°






Torx
T 20












Torx
T 20






SW22










Torx
T 20

















Torx
T 20











SW22

